

6, Maningham Pt.

Deane.

Bolton.

Lanes.

Mar 26/55.

J. P. Fidler, Esq

M/c. John Taylor & Co.

Loughborough.

Dear Sir,

I should be glad if you would kindly call at Deane when you are next in this area. We are having some difficulty with the rope positions 3, 4, 5. After watching this for some time, I am sure that it is necessary to move these ropes. The ringer on the 5th cannot see the 3rd rope at all, particularly at the Tail stroke when the 4th ringer's arms are outstretched. To my mind, I think it is necessary to move the 5th rope much nearer the 6th & move the 6th further round. I should be glad to hear from you regarding same.

Yours sincerely

W. B. Crook
