

JOHN TAYLOR & CO.

PHONE: 2241 (2 LINES)
TELEGRAMS: "BELLS, LOUGHBOROUGH"

CHURCH BELLS
PEALS-CHIMES
CARILLONS
CLOCK BELLS

RESTORING OLD OAK BELL FRAMES A SPECIALITY

THE BELL FOUNDRY,
LOUGHBOROUGH,
ENG.

5 September 1955.

M. Crook, Esq.,
6, Manningham Road,
Deane,
Bolton,
Lancs.


Dear Sir,

Deane Church.

Thanks for your letter. We should say that the slight mishap to the 2nd bell was caused through overpulling the bell and bumping the stay too hard on the slider which possibly then mounted the stopblock. It should be but a trifling matter to put right locally and we should be glad if you could get this done as we have no-one at liberty just now.

With regard to the tightening up of the nuts, bolts and greasers, we send to you a "steeple-keeper's guide" from which you will see that we point out there that whilst everything is new and bright the nuts must be tightened up periodically. We feel sure you will appreciate the fact that we cannot be expected to do all such small items of maintenance - that is only reasonable. We shall of course be only too pleased for our representative to call to look over the installation when next in the district if you wish us to do so.

Yours faithfully,



Enc.

U/JS.