

6, Birmingham Rd.

London

18th

1895

Sept 21/95

Mr. John Barber Mr. Secy

Dear Sir, Thank you for your of the 29th ult. I have carefully gone into this question & consulted Mr. P. Cook, the Land Pitt. Advisor. I now suggest that the following would considerably improve the circle:

Move the 3rd pipe 2" towards way from wall.

4th pipe 5th " 6 " " " " " " " 4 1/2 "

back towards the tower Screen towards about
same.

6th pipe 7" towards where the 7th is at

present.

7th pipe 10" into the old table hole.

I trust you will find these suggestions possible. May I also suggest when you come up to do this job, that you will give the fireplace a final lightening, as by now, it ought to have settled down.

Thanking you in anticipation,

Yours faithfully

H. Cook.